


**LEACHATE COLLECTION WELLS
INTERIM OM&M MONITORING AND BAILING DATA SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

DATE: October 26, 2006

TECHNICIAN NAME: HARKENSCHIED


TECHNICIAN SIGNATURE



WELL ID	BOTTOM OF WELL AFTER CONSTRUCT-ED [TOTAL DEPTH] (ft)	MEASURED BOTTOM OF WELL [TOTAL DEPTH] (ft)	GAUGING TIME		DEPTH TO LIQUID (ft)						HEIGHT OF LIQUID COLUMN (ft)		VOLUME OF LIQUID REMOVED (gallons)	COMMENTS
			Start	Finish	Start			Finish			Start	Finish		
					1 st Rdg.	2nd Rdg.	3 rd Rdg.	1 st Rdg.	2nd Rdg.	3 rd Rdg.				
LC-1	22.25	22.23	0730	0745	20.59	20.59	20.59	21.66	21.66	21.66				
LC-2	21.90	21.90	0800	0830	12.80	12.80	12.80	21.40	21.40	21.40				
LC-3	22.20													
LC-4	21.90	21.90	0845	0930	14.60	14.60	14.60	21.30	21.30	21.30				

W:\Interim_OM+M\LeachateCollectionWells\WorkPlan+FieldForms\October2006\Oct2606LC-WellsM&B(YF1).doc

**LEACHATE COLLECTION WELLS
INTERIM OM&M INSPECTION SHEET
WASTE DISPOSAL, INC. SUPERFUND SITE**

INSPECTOR'S NAME	INSPECTOR'S SIGNATURE	INSPECTION TIME	INSPECTION DATE
HARKENSCHIED		0730	October 26, 2006

ITEM OF POTENTIAL CONCERN	CONDITIONS OBSERVED				COMMENTS	CHECK (•) BELOW WHEN COMPLETED
	WELL ID LC-1	WELL ID LC-2	WELL ID LC-3	WELL ID LC-4		
Wellhead (well box, cover, gasket, concrete)	OK	OK		OK		✓✓✓
Well Casing and Cap/Plug	OK	OK		OK		✓✓✓
Liquid Present in Well Box	NO	NO		NO		✓✓✓
Other:						
Other:						
Other:						

W:\Interim_OM+M\LeachateCollectionWells\WorkPlan+FieldForms\October2006\Oct2606LC-WellsInspection(YF).doc

